





MBW103




MBW204






		MBW103	MBW204
1		4x	4x
2		4x	4x
3	T25 4,8x11,5 	8x	8x
4	MBW103 MBW204 	2x	2x
5	T25 M5x8 	4x	4x
6a	MBW103 MBW204 	4x	4x
6b		4x	---
6c	3,5x32 PH1 	16x	---
7	4,8x32 T25 T30 M6x20 	8x	16x
8	--- 6,4	---	16x
9	---	---	16x
10		1x	1x



www.striebelundjohn.com




Zubehör für		MBW103		MBW204	
		 (ZXM3010)		 (ZXM4010) (ZXM5010)	
		ZXM3005	ZXM3010	ZXM4010	ZXM5010
Z1		3x 30x5x150	3x 30x10x150	---	---
Z2		3x 30x5x180	3x 30x10x180	---	---
Z3		---	---	6x 40x10x246	6x 50x10x246
Z4	 M12  SW19	6x M12x25	6x M12x35	18x M12x35	18x M12x35
Z5	 A12	6x	6x	18x	18x
Z6	 (ZXM3005) T25 M5x12  T25 M5x20	6x	6x	6x	6x
Z7	 M12	---	---	6x	6x
Z8	 A6,4	6x	6x	6x	6x
Z9	 A5,3	6x	6x	6x	6x
Z10	 M8x25  SW13	---	---	12x	12x
Z11	 A8	---	---	12x	12x



		MBW103		MBW204	
Z12		3x 30x10x170 WZC2U	3x 40x10x170 WZC2U1	---	---
Z13		---	---	3x 40x10x250 WZC2U2	3x 50x12x250 WZC2W

		MBW103		MBW204	
X1		3x	3x	---	---
X2		---	---	3x	3x







MBW103







+ Z...





MBW103



2




3



4

6a

4x



7

8x



T25




②

T25




5 Nm



5

Z1

3x




Z12

3x



Z2

3x



Z4

6x



M12x35

Z5

6x



A12

X1

3x




①

SW19




60 Nm



6

6b

3x



6c

8x



PH1




3,5x32

①

PH1



3,5 Nm



7

Z6

6x



Z9

6x



Z8

6x




①

T25





3,2 Nm



8











10

1x



MBW204

1
4x



2

2
4x



3

8x





4,8x11,5 T25

2

T25




EDF 2 Nm
WR 5 Nm



3

4
2x



5

4x




M5x8 T25

1

T25




5 Nm



4

6a

4x



7

16x



8

16x



9

16x




②

T30



5 Nm



5


Z3

6x



Z13

3x



Z4

6x



M12x35

Z5

6x



A12

X2

3x




①

SW19



60 Nm



6

Z10

12x



M8x25

Z11

12x





A8

①

SW13



10 Nm



Z11

Z10

7

z5

4x



z6

8x



z7

4x




①

T25



3,2 Nm



8

10

1x

