



Connections

Diagram of the Connections block showing 12 pins. Pins 1, 4, and 5 are inputs with switches. Pins 8 and 10 are inputs with potentiometers. Pins 2 and 12 are outputs with LEDs. Pin 3 is 0V.

Connector

M12 with 12 pole
at the bottom

