



Connections

The diagram shows a 12-pin connector with the following connections:

- Pin 1: Input for a switch.
- Pin 4: Input for a switch.
- Pin 5: Input for a switch.
- Pin 7: Input for a switch.
- Pin 8: Input for a switch.
- Pin 9: Input for a switch.
- Pin 10: Input for a switch.
- Pin 11: Input for a switch.
- Pin 2: Output for a switch (indicated by a double arrow).
- Pin 6: Output for a switch (indicated by a double arrow).
- Pin 12: Output for a switch (indicated by a double arrow).
- Pin 3: Output for a switch (indicated by a double arrow).

Connector

M12 with 12 pole
at the bottom

